

LAB ID # 11216
LAB ID # 11827

Benchmark Analytics, Inc. Eastern Division

2566 Pennsylvania Ave.
Sayre, PA 18840

Phone: (570) 888-0169

Fax: (570) 888-0717

Work Order: 11050562

SEND DATA TO:

NAME: Dana Harris
COMPANY: Wellsville Water Treatment Plant
ADDRESS: 111 W. State Street
Wellsville, NY 14895

WO#: 11050562

PAGE: 1 of 1

PO#:

PHONE: (585) 593-3333
FAX: (585) 593-5864

TEST REPORT

PWS ID# 0200327-Allegany Co. DO

Drinking Water

RECEIVED FOR LAB BY: CMS

DATE: 05/04/2011 17:00

Page 1 of 1

SAMPLE: **Entry**

Lab ID: 11050562-001A

Grab

SAMPLED BY: DH

Sample Time: 05/04/2011 10:00

MCL

<u>Test</u>	<u>Result</u>	<u>Method</u>	<u>MCL</u>	<u>Analysis Start</u>	<u>Analysis End</u>	<u>Analyst *</u>
Total Organic Carbon	1.4 mg/L	SM5310C		05/11/11 9:38	05/11/11	KAL-SA

SAMPLE: **Source**

Lab ID: 11050562-002A

Grab

SAMPLED BY: DH

Sample Time: 05/04/2011 10:00

Reg

<u>Test</u>	<u>Result</u>	<u>Method</u>	<u>Reg</u>	<u>Limit</u>	<u>Analysis Start</u>	<u>Analysis End</u>	<u>Analyst *</u>
Total Organic Carbon	3.7 mg/L	SM5310C			05/11/11 9:38	05/11/11	KAL-SA

SAMPLE: **200 Bolivar Rd**

Lab ID: 11050562-003A

Grab

SAMPLED BY: BR

Sample Time: 05/04/2011 13:00

MCL

<u>Test</u>	<u>Result</u>	<u>Method</u>	<u>MCL</u>	<u>Analysis Start</u>	<u>Analysis End</u>	<u>Analyst *</u>
Asbestos	< 0.190 MFL	EPA 100.2	7	05/06/11 11:15	05/17/11	

Sample Note: Analysis performed by EMSL Analytical, Inc.

REMARKS:

Where the analytical method has been performed under NELAP certification, the analysis has met all of the requirements of the NELAC standard unless otherwise noted on the Analytical Report.

* CV = Benchmark Analytics, Inc. Center Valley, PA; SA = Benchmark Analytics, Inc. Sayre, PA

MANAGER

Amie M. Davis

DATE: 5/17/2011